



Fitting instruction

CONDENSER

Vehicle Type

All Vehicles

Working Instructions Condenser

WARNING



Please read this document carefully before replacing the Condenser, in order to fully benefit from the performance of your spare part over time. Installation must be carried out by a trained and qualified professional.

CAUTIONS BEFORE INSTALLING THE NEW VALEO'S SPARE PART

- Make sure to have identified the correct failure before fitting the new Condenser.
- Make sure that the packaging has not been damaged in transit.
- Make sure that you do not damage the product during unpacking it by using the appropriate means.
- The product must not be dismantled, modified or used for any other purpose than its original function.
- Before any repair on the vehicle, ensure that the engine is cold enough to work safely.
- While handling the Condenser, take special attention to the panels to not damage them. It would generate a drastic decrease of the performance.
- Before fitting the Condenser, confirm that its tubes match with the pipes and the fixing points with the ones on the vehicle.
- Ensure that the Condenser technology to be fitted is the same than the old one (with or without dryer).
- Make sure that only qualified technicians manipulate the A/C system. Use safety equipment required by your local and national regulations.

CAUTIONS DURING INSTALLATION OF THE NEW VALEO'S SPARE PART

- Make sure to recover the refrigerant from the loop by using the adequate A/C tool, the refrigerant is considered hazardous waste and must not leak into the air.
- Replace the seals and the dryer as the circuit has been opened.
- Ensure to tighten to the correct torque.
- To ensure the best performance of the new part, follow the requirements of the car manufacturer by cleaning the circuit, creating the vacuum and refilling the circuit with the recommended quantity and type of refrigerant and oil.

CAUTIONS AFTER THE INSTALLATION OF THE NEW VALEO'S SPARE PART

- Check for any signs of refrigerant leaks and ensure the correct function of the A/C system generating the recommended temperature in the cabin (measured at the grill) and that there are no abnormal noises.

VALEO disclaims liability for any damage caused by incorrect operation.
If the above conditions have not been respected, VALEO may refuse to cover the warranty following a failure of the Condenser.