



Technical Bulletin

DMF Module Kits

Vehicle Type

All vehicle models

STORAGE AND TRANSPORTATION OF DMF MODULE KITS

The Valeo Service UK Warranty department have received several claims with damage to both flywheels and clutch kits. Upon further inspection, damage can be seen to the internal packaging but no evidence of damage to the packaging externally.

Through further investigation, it has been found that the units returned have been stored and/or transported on their side and upside down rather than being lay flat. Due to the weight of the flywheels, Valeo Service highly recommend transporting and storing all clutch products containing a flywheel on a flat surface face up. Units that are transported or stored on their side or upside down risk the flywheel contacting other components in the box or unevenly distributing the weight of the product on one side. The uneven weight distribution can cause damage to components within the box.

